



FIG. 1








FIG. 5

Fig. 6

Fig. 7




FIG. 8








FIG. 10




Fig. 11







FIG. 12





This diagram shows a cross-sectional view of a corner joint. Two panels, labeled 36a and 36b, meet at a right angle. A third panel, labeled 36c, is positioned to cover the joint. A fastener, labeled 36d, is shown passing through panel 36c and into the corner where panels 36a and 36b meet.








FIG. 17








FIG. 20

